

chain link East 400' starts E. 50'

metal Post west 500' starts W. 50'

chain link West 200' starts W. 50'

West R.O.W. Fence 5100 W.

Metal Post Fence with P.I.s S. 500' N 200'

Cedar Post N 500' Ends @ Point

old Cedar Post N S. 1000' + 500' North

E. R.O.W. 5500 W.

Section Fence

E 2600' old cedar

W chain link 300'

E. cedar Post E. 500' + ^{200'} W. 500'

W cedar Post W. 500'

cedar Post E 300'

So. R.O.W. st. 5100 S. W. 300'

N. R.O.W. 5100 S.