

Roy Saunders
3330 W. 0 - 4000 S.

10/16/86

Slagowski
Balken

(2)

old wood posts ; cedar mixed running East ; South

newer wood ; metal posts w/wire leading west 80' fence
South

older cedar post w/barbed wire west (at least 30 yrs. old per
cedar changing to metal posts w/barbed
wire leading north. owner)

newer R.P. Tie fence w/ 2x6" cross boards

old cedar post w/barbed wire west cedar ; 6" diam posts west
runs west 600'

newer 6" diam. posts w/barbed wire East older cedar posts
runs East a long way w/barbed wire west

fence starts approx. 200' East of Row fence ; is older cedar posts
w/barbed wire (some R.R. Ties intermixed) cedar fence west

older broken fence w/cedar ; 6" intermixed w/wire
runs East to next Subd. cedar post fence west.

newer 6" diam. post w/wire fence running East 300'

cedar ; metal fence posts w/barbed wire running East 300'

newer 6" diam ; metal posts w/barbed wire running East 500'

newer metal post w/barbed wire running East 700'
older wooden posts as you continue East

newer metal post w/barbed wire running East 700'
older metal posts as you continue East