

I obliterate the marks on the standard cor. above described in accordance with instructions, and re-mark it S.C. and 6 grooves on the north face, and C.C. and 6 grooves on the West face,

I lay off from the true meridian an angle of 180° from North to west and run

South, along the fractional W. Edy of the Sp. Sect.,

Sec² 64 31,
descending along stony ground sloping S.

10.29 Intersect the Standard Cor. to Range T₂ 6ⁿ Range 4 E. as set by me established heretofore described.

Land mountainous.

Soil stony; 4^{1/2} data.

Mountainous land 10.29 chs.

July 17-1895.

This survey embraces a portion of the exterior of ~~the~~ T₂ 4ⁿ R. 4 E. and the closing indicates discrepancies beyond the allowable limit prescribed by "the Manual". Therefore to ~~discover~~ the error, and to ~~amplify~~ the I retrace as follows,

I (The above to be incorporated in the subdivisional field notes)