


9-26-83 Hillier, Butlers, Holmset

STA.

Uintah Highlands



$\pi @$

Additional ties & Reshot hill

~~4 ft.~~
~~28 + 34.8~~
~~28 + 57~~

B.S. 28+07 F.S. 29+07 ($169^{\circ} 47' 05''$)

$249^{\circ} 47' 08''$

~~27 + 09.6~~
~~27 + 20~~

B.S. 26+73 F.S. 27+57 ($133^{\circ} 22' 42''$)

$213^{\circ} 22' 35''$

~~34 + 34.8~~
~~34 + 57~~

B.S. 33+57 F.S. 35+07 ($36^{\circ} 20' 00''$)

$216^{\circ} 20' 09''$

~~36 + 34.8~~
~~36 + 57~~

(Ties to Inlets)

B.S. 34+57 F.S. ① North 51.38'

($285^{\circ} 34' 06''$)

② South 436.75'

($150^{\circ} 13' 02''$)

(next page)

				# of south Inlet
		12.61	4579.74	
	3.04	4591.45		
T.P. #3		11.39	4593.39	on Rock
	1.62	4604.78		
T.P. #2		9.82	4603.16	on Rock
	0.93	4605.98		
T.P. #1		7.64	4612.03	on top of stake
				<u>4617.9'</u>
	1.72	4601.03	1.7	<u>23</u> <u>26</u>

STA.

B.S.

H.I.

F.S.

Elev.

Remarks