

7+00

5.20

7+50

5.19

8+00

5.34

8+50

5.31

102.86

T.P.

5.31

97.55

5.70

103.25

9+00

5.82

9+50

5.78

10+00

5.95

10+50

6.15

11+00

6.24

11+50

6.28

12+00

6.31

12+50

6.37

13+00

6.37

13+50

6.53