

Remarks

10-21-77

52

#3 Beatrice Sub on 2000w & 700S.  
does not have Site improvement or  
complete Bond other than 2 Fire Hydrants  
at a cost of \$900.00 each, total of \$1800.00  
ditch on 700S. requires 18" CMP pipe  
for 342 feet should follow up.