

1 Hr

① Placed 5675 S. Woodland Hills #2
for signs

2 hrs

② Re-checked Liberty Bell Sub as to
progression on any work (None) checked
Upper Valley on Check Holes & Eds.

1 Hr

③ Spent 1 Hr at DDO w/ Sam Welby to
get started on outside Rail

4 Hrs

④ Made Re Call on Jim Sturull to
expidate Water Boxes on Raintree Sub
& went thru entire Area for any
work needed before winter set in