

8-12-82 North Fork Rd, Hillier Holmes
 alignment

- Ties to Thealls from original "B" line (RIGHT ANGLES)
 off (1. off E of "B" line (original) P.T. } $\sqrt{46.6'}$ To Mail Box #8
 (2. $\sqrt{30'}$ To E of existing North Fork Rd.
 $\sqrt{3.}$ Telephone Junction Box 55'
 4. 47' To Garage
 $\sqrt{5.}$ 95' To shed
 $\sqrt{6.}$ 69' To Water Meter
 $\sqrt{7.}$ 110' To house

Hor. & Rt. Ties from P.T. To Thealls.

- $\sqrt{1.}$ 57° 49' to shed S.W. & Rt.
 $\sqrt{2.}$ 97° 20' To house S.W. CORN.
 $\sqrt{3.}$ 33° 22' To prop. corner N.W.
 $\sqrt{4.}$ 36° 14' To Water Meter
 $\sqrt{5.}$ 53° 03' To shed N.W.
 $\sqrt{6.}$ 72° 30' To N.W. Garage
 $\sqrt{7.}$ Mail Box (Tele. Junction) (Bx) 9 S.W. (Garage 90° #9)
 To P.T.

E. of W. { 306.35 Hub 304.60
 .30 {
 1.00' { 306.00' Rebar

306.00
 304.60

 2.40