

MC-52
TSW. R2W.

X @ Hub & Tack B.S. # 415 N. $\frac{1}{4}$, 18 F.S. \rightarrow
RT $\&$ $35^{\circ} 58' 30''$ Vert $\&$ Flat #57 \downarrow
Hor. Dist. 2707.92'
CORR. DIST. 2674.37'
Computed

X @ wit. Mon. 49.30' west N $\frac{1}{4}$ 18
Hor. Dist. To N.W. $\frac{1}{4}$ sec 18
Vert $\&$ Flat again
Hor. Dist. (Corrected)
2674.30'

X @ E $\frac{1}{4}$ cor. sec. 18
Hor. Dist. To Center sec. 18
Corrected Dist. 2651.89'
Vert. $\&$ Flat. again

— 5/19-82 — (North)

X @ Hub & Tack 240.78' from
wit. Mon. 62.04' west of Center Sec.
18.

Hor. $\&$ RT. B.S. Wit. Mon.

F.S. W $\frac{1}{4}$ cor. sec. 18

$88^{\circ} 20' 45''$ (Double $\&$ $176^{\circ} 41' 15''$)

Hor. Dist. From Hub & Tack to Wit. Mon.
240.78'

Hor. Dist. From Hub & Tack to
Wit. Mon. 100.5' from W. $\frac{1}{4}$ cor.
2716.05'

Corrected Dist. center to West $\frac{1}{4}$ cor.

2673.70' Vert $\&$ Flat.