

#5 270° 07' 50" T @ S.W. cor. sec. 34
 90° 07' 37" ⁴³ B.S. S 1/4 cor. sec. 33
 179° 59' 41" F.S. W 1/4 cor. sec.
 90° 07' 33" ⁴⁴ 3 T. 5 N. R. 2 W.
 270° 07' 42" ⁴⁷ (45")
 359° 59' 42" (89° 52' 15" av.)

#6 90° 10' 16" T @ S.W. cor. sec. 34
 270° 10' 11" B.S. S 1/4 cor. sec. 33
 179° 59' 50" F.S. W 1/4 cor. sec. 34
 270° 10' 14" T. 6 N. R. 2 W.
 90° 10' 11"
 180° 00' 00"

#7 180° 01' 39" T @ S.W. cor. sec.
 00° 01' 39" 34
 180° 00' 08" B.S. S 1/4 cor. sec. 33
 00° 01' 41" F.S. S 1/4 cor. sec. 34
 180° 01' 40"
 180° 00' 10"

180° 01' 41" av.

3-10-83 Hillier Holmes
 Section 32 T. 6 N. R. 2 W.

#1 269° 53' 08" T @ N.W. cor. sec.
 12" 89° 53' 16" 32
 180° 00' 05" B.S. S.W. cor. sec.
 10 11" 89° 53' 14" 32
 269° 53' 10" F.S. N 1/4 cor. sec. 32
 90° 06' 49" av. 180° 00' 02" (269° 53' 11" av.)

#2 179° 48' 35" T @ N 1/4 cor. sec. 32
 40 359° 48' 44" B.S. N.W. cor. sec. 32
 180° 00' 08" F.S. N.E. cor. sec. 32
 1/4 359° 48' 42" (179° 48' 38")
 26 179° 48' 38"
 00° 00' 03"