

Standard Measurements - Quincy Ar

from 25th to 24th

32	0.18	98	98	-000 +004+004	32.004
100	0.10		100	-005 +007+002	100.082
300	0.10		77	-002 +059+007	300.057
34.64	0.10		97	-000 +004+004	34.644
100				+147	766.787

= final corrected measure

from 24th to 25th

B43

36.00	0.10	100	102	-000 +006+006	36.006
100	0.10	102	102	-000 +023+023	100.023
200	0.10	100	101	-001 +045+044	200.044
200	0.10		102	-002 +046+044	200.044
200	0.14		102	-002 +048+046	200.046
30.59	0.00		101	-000 +005+005	30.595
				+168	766.758

= final corrected measure