

Δ @	N/E	8-15-88	ARAVE	BUTTARS
PLEASANT	D	0° 00'	10.6 ¹⁰ 10.7	10.65 17.82
	R	180° 00'	25.2 24.8	25.00
LEWIS	D	41° 59'	51.5 52.2	51.85 56.92
	R	222° 00'	01.8 02.2	02.00
			39.10	
PLEASANT	D	11° 00'	25.1 ²⁵ 25.2	25.15 33.62
	R	191° 00'	42.2 42.0	42.10
LEWIS	D	53° 00'	09.5 08.7	09.10 14.05
	R	233° 00'	19.2 18.8	19.00
			40.42	
PLEASANT	D	22° 00'	35.2 ³⁵ 35.0	35.10 42.20
	R	202° 00'	49.0 49.6	49.30
LEWIS	D	64° 00'	16.8 16.2	16.50 20.42
	R	244° 00'	24.5 24.2	24.35
			38.22	
PLEASANT	D	33° 00'	50.6 ⁵⁰ 50.8	50.70 57.20
	R	213° 01'	03.6 03.8	03.70
LEWIS	D	75° 00'	28.3 28.0	28.15 34.28
	R	255° 00'	40.0 40.8	40.40
			37.08	
PLEASANT	D	45° 02'	09.1 ¹⁰ 08.7	08.90 13.52
	R	225° 02'	17.9 18.4	18.15
LEWIS	D	87° 01'	48.9 49.4	49.15 54.82
	R	267° 02'	06.6 00.4	00.50
			41.30	
PLEASANT	D	56° 00'	25.6 ²⁵ 25.6	25.60 33.42
	R	236° 00'	41.0 41.5	41.25
LEWIS	D	98° 00'	09.1 08.7	08.90 12.82
	R	278° 00'	16.4 17.1	16.75
			39.40	