

PLEASANT	D	67° 00'	35.5 ³⁵	36.0	35.75	41.22
	R	247° 00'	46.4	47.0	46.70	
LEWIS	D	109° 00'	17.8	17.7	17.75	22.35
	R	289° 00'	27.1	26.8	26.95	
			41.18 ³⁰			
PLEASANT	D	78° 00'	49.7	49.2	49.45	54.58
	R	258° 00'	59.7	59.7	59.70	
LEWIS	D	120° 00'	25.0	25.4	25.20	30.20
	R	300° 00'	35.4	35.0	35.20	
			35.62			
PLEASANT	D	90° 04'	11.0	10.0	10.50	18.55
	R	270° 04'	26.0	27.2	26.60	
LEWIS	D	132° 03'	49.8	50.3	50.05	55.92
	R	312° 04'	01.9	01.7	01.80	
			37.38 ³⁵			
	D	101° 00'	26.4	26.0	26.20	36.20
	R	281° 00'	46.2	46.2	46.20	
	D	143° 00'	09.2	08.7	08.95	13.52
	R	323° 00'	17.8	18.4	18.10	
			37.33 ³⁰			
	D	112° 00'	36.4	36.8	36.60	43.08
	R	292° 00'	49.3	49.8	49.55	
	D	154° 00'	17.9	17.4	17.65	23.18
	R	334° 00'	28.4	29.0	28.70	
			40.10			
	D	123° 00'	50.4	51.0	50.70	54.72
	R	303° 00'	59.1	58.4	58.75	
	D	165° 00'	25.7	25.8	25.75	31.58
	R	345° 00'	37.5	37.3	37.40	
			36.85			