

The Summit at Ski Lake No. 9

A part of the Northeast 1/4 of Section 24, T6N, R1E, SLB & M, U.S. Survey
Huntsville District, Weber County, Utah
March 2007

Northwest corner of Section 24, T6N, R1E, SLB & M, U.S. Survey Found Bureau of Land Management Good Condition. (0.5' above ground) Brass Cap - (1967)

North 1/4 corner of Section 24, T6N, R1E, SLB & M, U.S. Survey Found Weber County Brass Cap - (1991) Good Condition. (0.5' above ground)

(Section line)
S 89°36'57" E
(S 89°36'44" E W.C.S.)
2660.60'
Calc. from measurements
(2660.83' W.C.S.)
(Basis of Bearing)

