

1-25-89

U.S.F.S.

1972

Brass Cap
2" Alum Pipe

Rock outcrop

Clump Scrub oak

Located in
Clump of Scrub oak
on 35° slope

Post 4x4"
8' NW
of Brasscap

270.0

N. Ogden Divide Rd.

Guard Rail



⌈ @ 22 A B.S. $\frac{21}{22}$ | $\frac{28}{27}$ 0°00'00"

X RT to Fence

- 1. 72° 52' 20" 55.38'
- 2. 126° 02' 05" 67.55'
- 3. 116° 44' 30" 88.08'
- 4. 185° 22' 55" 41.90'

