

Jan 30 - 1910

Level notes taken for Lynne Irrigation Co. on James Stones Farm in Lynne - Dec. 17 + 18 - T.P.G. - N.R.L.W. for the purpose of ascertaining drainage conditions on said farm.

(1)	+ 6.9	4266.9	
(2)	6.2	4273.8	in bottom of spring run just north of Stones barn yard in pasture on box culvert at same point abt 600' W. of Slough " 200 W. of last reading in Slough again - " Lynne ditch where same runs into Slough from South " " " on N. side of 2 nd Street
(3)	4.6	4269.2	
(4)	5.0	4268.8	
(5)	7.1	4266.3	
(6)	7.5	4266.3	
(7)	7.4	4266.3	
(8)	6.2	4267.0	
	- 5.9	4267.9	
	+ 4.8	4272.7	
(8)	7.3	4265.4	in slough
(9)	7.7	4265.0	" "
	- 6.8	4265.9	
	+ 4.8	4270.7	
(10)	3.5	4267.2	on Stones farm land
(11)	6.6	4264.1	in Slough
(12)	7.5	4263.2	S. End of cross-cut ditch north
	- 6.3	4264.4	
	+ 5.2	4269.6	
(13)	5.9	4263.7	Surface of water at Rail Road Culvert true E/ 4263.4 by Lantz
(14)	2.2	4267.4	on O.S.L. Rail Road, true S/ 4267.0 at Sta. 44+33
(15)	7.2	4262.4	Surface of water at North culvert
(16)	3.2	4266.4	on O.S.L. Ry track at North culvert

