

# North Fork River Bridge

## Work

Removed concrete Forms  
From center pier uncovered  
West abut and melted snow  
Began excavating for East  
abutment - (Tractor broke down)