

2 1/2 hr

- ① Inspected Randall Area #3 for new part of present sub #2

5 1/2 hr

- ② Inspected Circle R sub Hope Park laid mulch job completed good 3" laid compacted to 2 1/2"

1 hr

- ③ Inspected Lower Valley Roads for chink holes & turned them into roads kept for repair