

23^d Street N. S.

June 29th 1899

Half Block East from Hall and in
poor repair. Balance to Lincoln Ave
in good shape. =
#

Between 256 & 262 One bad Hole
Stump sticking up may be
dangerous. Should be cut out
and walls fixed up.
#

North Side from Lincoln To Grant in
good order except as noted above
#

Corner West Ave & 23 North side
and East of Grant Outside plants
protruding. Should be cut down,
#

Front of 324 & 330 in poor
repair
#

362 Bad hole West of fence post
West.
#

Pay Block in course of erection
Walls are broken up.

Balance South as noted from
Grant to Washington N. S., 23^d Street
in fair condition
#