

Side Walks — June 29-1894

Grant Ave. N. Side

2539 Crossing North Side in bad repair  
#

2543. on property lines in bad repair  
#

2549-2547 bad repair  
#

2559 bad condition  
#

2562 - 2567 - 2573 - See Gibson Aft  
in hands of receiver -  
walks in poor condition  
#

City Fair Station in bad condition  
full of holes - should be repaired  
is dangerous to men & horses  
#

Washington Ave. West Side 26<sup>th</sup> to 27<sup>th</sup> St.

2613. One Dangerous hole at Gate  
#

2647 bad Hole at Gate and in poor  
condition at Machine Shop -  
#

From 2667 to 27<sup>th</sup> Street in poor condition  
#

Balance full of cracks from 26 to 27<sup>th</sup>  
#

Dangerous Hole in waterway south of  
27/01  
#

2717 a number of bad cracks & all  
holes  
#