

Side Walk

June 29-1899

From 27th Street North in Washington
East Side -

2684 several small holes & cracks
in poor condition

2678 Two small holes and a number
of cracks across walk, poor

2652 One large hole and tree stump
on curb line

2620 A number of cracks & holes - poor -

From Above number to 26th Street
full of cracks and holes and rough

From Above Street to 26th Street
Imperial Company in poor condition
full of cracks & holes.

2540 Sidewalk across crossing bad
projecting stones

2530 broken & rough in poor condition

Grand Open Structure a very dangerous
trap door in Walk

2486 In bad condition 2 large holes
and street washer projecting 6 inches above
walk. The Rain Fall Block

Union Light & Power Co poor

2470 In bad condition - full of holes

2464 In Bad Condition } rough
2462 " " " } and full
of holes