

Side Walks

June 29th 1899

East of Jefferson to Quincy no water
otherwise known or very rough

From A. W. Mads Plumbing Shop east
to Adams Ave. Remains back badly
broken and dangerous

Reed Hotel Cor. East of Hotel
at Laundry in Bad Condition
#

July 3rd 1899

Received of J. E. Batchelor:-

One Solid Lime Rock 25th W. P. D. No 3 = Cub. ft.
10' Long 3.5' W. 1.5' H. = 52.50

July 5 - 1899

William James
One Solid 13.5" x 3.2" x 1.2"

John Johnson
One Solid 13.5" x 3.5" x 1.2"

"1 Solid 13.5" x 3.5" x 1.5"