

Sept 25<sup>th</sup> Afternoon

Center manhole between 25<sup>th</sup> & 24<sup>th</sup> St on Washington  
Manhole in good condition. Water flowing freely  
Some mud in bottom. Float ~~could~~ brought  
down from this manhole to one at  
23<sup>rd</sup> and Washington Ave  
lights burning, no leaks to be seen  
Sewer in good condition

Manhole at 24<sup>th</sup> and Washington Avenue  
Manhole in good condition. Some mud  
in bottom. Float started from this  
manhole met along 24<sup>th</sup> St  
float having enough to enter manhole on 24<sup>th</sup>  
lights burning in both directions.  
Sewer in good condition

Page 48 & 63

Sept 26<sup>th</sup> 1891 AM.

48

Center Manhole Washington Ave bet 23<sup>rd</sup> & 24<sup>th</sup>  
<sup>at the blind end</sup>  
no water running between this manhole  
and the manhole at 24<sup>th</sup> and Washington Ave  
This manhole in good condition. some  
mud in bottom. Started float  
north to manhole at 23<sup>rd</sup> and Wash-  
ington Ave. So much sediment in  
bottom of sewer for float to pass  
through no leaks as far as known

23<sup>rd</sup> and Washington Avenue  
Manhole in good condition  
not enough water running to  
carry off sewage. started  
float met along 23<sup>rd</sup> not enough  
water to carry float without damming  
Sewer along 23<sup>rd</sup> to center manhole from  
Washington Ave <sup>met</sup> made slushing badly  
No leaks to be seen. Could see lights  
plainly through sewer