

Flush Tank on Washington Ave  
at N line of 2<sup>nd</sup> St.  
In good condition

Center Manhole Washington Ave  
between 2<sup>nd</sup> and 2<sup>nd</sup> 1/2 St.

No water passing through sewer  
Manhole in good condition  
Some mud in bottom that has  
fallen through plate.

Could not get float from this  
manhole north to manhole  
on 2<sup>nd</sup> St and Washington Ave

49  
Sept 28<sup>th</sup> 1891 P.M.  
Center Manhole 2<sup>nd</sup> 1/2 St between  
Washington and Grant  
Manhole in good condition  
no perceptible difference in  
wet and dry bricks.  
Good flow of water in sewer  
started float at Grant. Passing through  
to manhole at W 2<sup>nd</sup> 1/2 St and Grant  
no leaks to be seen.

Manhole at 2<sup>nd</sup> 1/2 St and Grant  
Manhole in good condition  
No difference in bricks.  
good stream of water running  
through sewer. small stream  
coming in sewer from South  
No leaks to be seen. Sander  
running all the way.