

25th St and Lincoln
Manhole in good condition
No difference in brick all good
No leaks to be seen

Center Manhole 25th St between
Lincoln and Grant
Manhole in good condition
No difference in brick all good
No leaks to be seen
Considerable sand in bottom

55
25th St and Grant Avenue
Manhole in good condition
No difference in brick all good
No leaks to be seen

Center Manhole on 25th between
Grant and Washington
Manhole in good condition
No difference in brick all good
No leaks to be seen