

Center Manhole on Lincoln  
Between 2.4 and 2.3<sup>d</sup> Eto  
Manhole in good condition  
no difference in bricks all good  
no leaks to be seen

Center Manhole on Lincoln  
Between 2.2<sup>d</sup> and 2.3<sup>d</sup>  
Manhole in good condition  
no difference in bricks all good  
no leaks to be seen

October 12 1991 P.M.  
Wall Avenue 27<sup>th</sup>  
Manhole not in good condition  
bricks hard and good but  
several leaks inside of man-  
hole about 10" from table  
Small leak at the junction of brick  
and blind end of sewer pipe  
on the South. Blind end on  
East leaking some,  
3 leaks about 2.0' north of this  
Manhole. not enough water to  
run float, crawled down to leak  
South of leak about 5' some decayed  
brick on East side of sewer