

Center Manhole on Wall

Between 2.6 and 2.8^{1/2}

Manhole in good condition.

No difference in bricks. All good
condition. No leaves to be
seen

Wall and and 2.5^{1/2}

Could not move cover.

passed nothing through from
Manhole bet - 2.6 and 2.8 to
Manhole bet 2.4 and 2.5^{1/2}

Center Manhole Wall and ⁵⁹

Between 2.5 and 2.8^{1/2}

Manhole in good condition

No difference in bricks all good
No leaves to be seen. good stream

2.8^{1/2} and Wall

See notes on 2.8^{1/2}

Center Manhole on Wall bet

2.3 and 2.4^{1/2}

Manhole in good condition

No difference in bricks all good

No leaves to be seen

good stream of water

2.3 and Wall

see note on 2.3