

11 Manhole out from wall
Manhole in good condition.
No leaves to be seen.
The sediment
Correct all good to difference
and stream

Outlet of Sewer in good
condition. Correct
all good but no leaves
to be seen