

May 10th 1900

By order Mayor Browning take some
men from Street Supervisor Saunders
and inspect city water pipe.

Start at 1 P.M.

Geo. Masfoll
Jas. Shadhill
W. F. St John
John Hassell
Amos Knechtley
W. M. Foster.

A. White
No 1 23^d St 100 W of S. B Moffitt Lane 3 1/2 ft. 6"

good condition small spots rust seem to form on
outside but scale of scaling no sign of rust below.

No 2 23^d St 24 ft. E. of S. B Moffitt Lane 3d 6"

good condition.

No 3 23^d St. 59 E. of S. B. Moffitts Lane 3d 6"

good condition

Started 7 holes above Adams but could
not find pipe at 5 P. M. so filled
up holes and quit

May 11th 1900

Went to exp. 2910 Wash

John Hassell
W. Hatch
John Aborn
W. H. Lyday

