

Lincoln Ave South from
No of Holes Dist Paces Remarks

Grant Ave South from
#24
1 Dist paces 6" pipe
• Struck 72" wide for length

#25
of next pipe 9' good
6" pipe

#26
3
Soil yellow clay
6" pipe

#27
top + bottom
Pipe exposed
light clay

25 Property Line

35

24 st Property Line

Exposed for 6ft - slight rust
exposed soil sand & gravel 25%

Exposed for 3 ft - indications
soil Black muck 10%

Exposed pipe 6' good no rust
- 10%

for 6ft numerous rust spots
and sandy soil
40%