

#84 ✓
20th St. 90 ft. West of Jefferson

#85 ✓
21st " 100" " " "

#86 ✓
Adams Ave 250th N of 22nd 6" pipe

#87 ✓
Adams Ave 85 ft S of 22nd 6" pipe

#88 ✓
22nd Street 85" W of Adams 6" "

#89 ✓
" 135th E " " 6" "

#90 ✓
" 485th E " " 6" "

#91 ✓
73rd " 500th E " " 6" "

#92 ✓
" " 150th E " " 6" "

#93 ✓
24th St 90 ft N of Adams 6" pipe Sand

#94 ✓
24th " 185 ft E " " 6" pipe Good

#95 ✓
Adams Ave 115 ft S. of 24th 6" pipe good

#96 ✓
Adams Ave 75th N of 25th St. 6" pipe -

Dry loam, good pipe

Wet sand, much rust, pitting starting
but not far developed 12 1/2 %

Good condition Soil wet sandy loam

" " " very wet " "

" " " " " Clay

" " " wet sand

" " " " "

" " " dry sand

considerably pitted Soil Loam dry 25 %

surface rust - pitted
and gravel and clay damp 15 %

Good condition Soil Sand and gravel dry

Condition Soil sand and gravel dry

Good condition Soil dry sand