

- #139 ✓
27th St 215th E of Jefferson Ave. 6" pipe rust and several pits
Soil dry sand 40% 50
- #140 ✓
Jefferson Ave 125 ft N of 27th 6" pipe. in fair condition - Soil dry sand 10%
- #141 ✓
" " 35 ft S. of 26th 6" pipe. good condition - Soil dry loam
- #142 ✓
26th St. 210 ft W of Jefferson Ave. 6" pipe. fair condition - Soil wet sand
- #143 ✓
26th St. 260 ft E. of Jefferson Ave. 6" pipe. at joint good condition - also a connection to #631
badly rusted around connection
soil rust around joint Soil Loam 20%
- #144 ✓
Jefferson Ave 236th N. of 26th St. 6" pipe. rust some fine pits - Soil dry sand 30%
- #145 ✓
Jefferson Ave 90 ft S. of 25th St. 6" pipe. con. Siderable rust no pits Soil dry sand 20%
- #146 ✓
25th St 290 ft N. of Jefferson Ave 16" pipe. much rust top and bottom - fitted -
"wrought iron" Soil sand + gravel 33 1/2%
- #147 ✓
25th St. 285 ft E of Jefferson Ave 16" pipe. wrought iron. rust top and bottom - fitted -
Soil sandy loam 33 1/2%