



Oct. 28 - 1890

20

Cut, evidently washed into Pond
~~bank~~ of Ogden Milling & Elevator
 Co's Mill from Cemetery, drains from top
 of bank to pond, is about $10 \times 15 \times 15$ ft
 equivalent to $833\frac{1}{3}$ cu. yds. of sand.

I should estimate that at least 1000 cu
 yds had been washed in, or at least had
 been moved. Much stopped at foot of bank, forming
 a talus between bench & pond.

Pond said to have been here an
 average of $4\frac{1}{2}$ ft depth (Jos. Clark as
 authority) 20×60 ft ^{A. F. PARKER} filled to surface -

I estimate that an area = 50×125
 ft has been covered by sand equal to an
 average thickness of 2 ft. = 463 yds.

As much light material has no doubt
 reached further, I think 500 yds a fair
 estimate of material deposited