



MARRATIVE

This survey was requested by Mr. Albert Warner on behalf of the Weber Wildlife Federation for the purpose of establishing a number of points on the Federation's (East Boundary) common boundary with Mr. Scott Waterfall. Monuments were found at all four property corners as depicted on this drawing. A line bearing North 344° East between the monuments at the Southwest and Northwest corners of the Section was used as the basis of bearings. East Property Line was monumented as shown on this Drawing.

I, Jay E. Anderson, do hereby certify that I am a Registered Land Surveyor and that the above description was made as a survey of the above described property. I further certify that the above plat correctly shows the true dimensions of the property surveyed.

Description

The west one half of section 5, T2N, R1E, S28W, R.S. Survey, Contains 311.95 acres.

- Set rebar & Brass Cap on Property line with metal post marking location.

2 May 1977

Jay E. Anderson

RECEIVED
MAY 02 1991
Weber County Surveyor

REVISID 12-21-90

GREAT BASIN ENGINEERING & SURVEYING, INC.
Weber County Surveyor

Property Survey
Water Middle Restoration

OWNER: B.P.	SCALE: 1"=200'	CHECKER:	DRAWN UP:
DATE: 12-21-90			25-20-92