

PERC TABLE				
HOLE #	DEPTH, in.	SOILS EVALUATION WEBER COUNTY HEALTH DEPT. #15456		
1	0-21"	Sandy Loam, Granular Structure		
	21-40"	Sandy Loam, Blocky Structure		
		Groundwater Encountered at 40"		
2	0-27"	Sandy Loam, Granular Structure		
	27-50"	Sandy Loam, Blocky Structure		
3	0-23"	Sandy Loam, Granular Structure		
	23-46"	Sandy Loam, Blocky Structure		

Exist. Barn/Shed		
299.67'		
I50.00' S 0°38'01" W		
Landmark Surveying, In	c. 4646 South 3500 West - #A-3	in the State of Utah 2 known as the made a survey of measurements, the field notes r contained in lied, are hereby r warranties adjacent dary with the certify that, to the the Land Use
www.LandmarkSurveyUtah.co DEVELOPER: Ken Iverson	ice West Haven IIT 84401	5 SURVEY
SW 1/4 of Section 32, Township 6 North,	Subdivision	RECORD OF SU
	I Tyler D. Knight, do hereby certify that f 1080000 108000 108000 108000 108000 108000 108000 108000	Supervised in the second of the second secon